



Facility and Capital Plan

Between May 2020 and December 2020, Connect Charter School undertook major renovations including a (partial) new roof, parking lot, learning commons upgrade and new main office. Below is a prioritized list of facility and capital needs for Connect Charter School.

| Capital Requests | Description | Priority (1- high, 3-low) | Cost |
|------------------------------|--|---------------------------|-------------|
| Field Experience Site | The school requires a field-experience site for outdoor and land-based learning opportunities. | 1 | \$1,000,000 |
| School Envelope | Brick masonry on the envelope of the school is compromised in a number of areas. Some windows in the school are the original (1965) single glazing, in anodized aluminum frames in poor condition. | 1 | \$650,000 |
| Windows and Interior doors | Original (1965) doors inside the school need to be replaced. | 2 | \$300,000 |
| Interior Painting | Classrooms and hallways need to be painted. | 3 | \$80,000 |
| Gymnasium and stage flooring | The gymnasium and stage floor need to be refinished. | 3 | \$75,000 |